


## WILCO TRUCK & TRAILER FRAMES – HØNEFOSS – NORWAY

The **WILCO** Company (Mr. Nils HAFNOR) in Hønefoss , Norway, is making truck & trailer frames. All year long Norway and the other Scandinavian countries can be hit by very cold winters (but also by very hot summers) and they use a lot of road salt in the winter season. Therefore, **WILCO** is using **ZINGA** as their basic corrosion protection since many years. Below you will view some photos of the extraordinary behavior of **ZINGA** in this harsh region.



**ZINGA** was used in 2007 for this frame. These pictures were taken in 2018.



The rusted brackets were Not protected with **ZINGA**



System:  
 Surface preparation: Blasting to SA 2,5  
**ZINGA** 1 x 60 µm DFT  
 Topcoat (different brands) 2 x 100 µm DFT





This frame was built in December 2010. These pictures were taken **10 years after**, in October 2020, after having traveled 1,000,000 km ! (the visible heavy rusted parts were protected with a traditional paint system and DINITROL.)

